

SMITHFIELD POWERSPORTS

506 S. Brightleaf Blvd. Smithfield, NC 27577

SmithfieldPowersports.com

919-300-1670 / SPS@SmithfieldPowersports.com



Unit SXS - CFM 2016 ZF800

Address:

Reason / Problem:

Turns over, won't start

VIN :



Parts / Materials

Quantity

Description

Amount Per

Cost

Total Parts Cost:

Labor Cost:

210

Shop Supplies:

Tax:

DISCOUNT

Total Cost:

210

Work Performed:

Compression test on both cylinders

Rear cylinder failed test with 0psi.

After further inspection, found that the rear camshaft gear was spun loose from crank.

Also found that rear cam chain was kinked

Cause of problem appeared to be the cam chain tensioner. Found that the spring inside tensioner was mangled.

Mechanics Notes:

Picking up AS IS/NOT REPAIRED to have warranty performed at dealership purchased from.

Reassembled unit at customers request.

DO NOT TRY TO START UNIT. DOING SO COULD CAUSE FURTHER DAMAGE!!!

Customer Notified:

05/23/17

WBH: 05/23/2017